Division of Oil, Gas, & Mining Mining Report 01/22/96 MINE ID: M0150030 MINE NAME: SINBAD MINE OPERATOR: SINBAD MINING CORP. CONTACT: MR. W.L. WILSON ADDRESS: 101 S 3RD ST STE 101 GRAND JUNCTION CO 81501 PHONE: (303)243-7806 Surface Owner: BLM BLM #: Mineral Owner: BLM Lease #: Qtr-Qtr-Qtr1 Qtr-Qtr1 Qtr1 Qtr-Qtr2 Qtr-Qtr2 Qtr2 Sec Town Range 35 22.0S 10.0E Permit Status: APP Mine Type [(S)urface, (U)nderground]: U 110 Mine Status: SUS Acreage: Status Date: / Minerals Mined TENTATIVE APPROVAL FINAL APPROVAL LAST INSPECTED DATE RECEIVED DATE DATE 04/07/80 12/24/79 02/28/80 10/18/95 BOND TYPE: SURETY BOND BOND AMOUNT: \$\$\$\$16,225 ANNUAL REPORT YEAR: 95 YTD Total NONCOMP NOTICES: 0 0 DATE ISSUED: DATE RESOLVED: VIOLATIONS: 0 0 DATE ISSUED: DATE RESOLVED: REVISIONS: 0 0 0 DATE REC'D: DATE APPROVED: DATE REC'D: AMENDMENTS: DATE APPROVED:

COMMENTS:

MRC ORIGINALLY PERMITTED THIS SITE. THE NOI WAS TRANSFERRED TO THE CLAIM HRC ORIGINALLY PERMITTED THIS SITE. THE NOT WAS TRANSFERRED TO THE CLAIM HOLDER (BILL WILSON) IN THE FALL OF 1982 WHEN THE MINE WENT ON STANDBY. INTERIM RECLAMATION WORK WAS PERFORMED AT THIS TIME ALSO. THE MINE WAS REOPENED BY A LESSEE IN LATE 1985. IT APPEARS THAT THE MINE MAY AGAIN BE ON STANDBY.

1992 REPORT STATES THAT @2 ACRES ARE DISTURBED. MINE STILL ON STANDBY STATUS.

1993 REPORT STATES THAT @1 ACRE IS DISTURBED. CLEANED UP TRASH & REMOVED MINE BUILDING IN 1993. UNKNOWN FUTURE OF MINE. VISIT 10/95 FOR RECLAMATION DETAILS